WPA RESOURCES WARRANTING FURTHER STUDY FOR NATIONAL REGISTER

BECKHAM COUNTY

(Region 7)

	Property Name	Location	Town	Photo Ref.
1.	School Teacherages	SE12, T8N, R24W	Delhi	7BEC3a-f
2.	Ackley Park Stadium	3rd Street	Elk City	7BEC6a,b
3.	Ackley Park Wall	Ackley Pk Dr & 3d	Elk City	7BEC7a,b
4.	Elementary School	Cedar & 4th	Erick	7BEC10a,b
5.	Agriculture Building	114 E. Enterprise	Sayre	7BEC14a,b
6.	Sayre Bathhouse	T9N, R23W, NW4	Sayre	7BEC17a-c
7.	Sweetwater School	T11N, R26W, NE26	Sweetwater	7BEC18a-f
8.	Merrit School Gym	T11N, R22W, SE36	E. City vic	7BEC13a-d
9.	Home Ec. Bldg.	T19N, R22W, SE34	Carter vic	7BEC19a,b

HISTORIC PRESERVATION SURVEY INVENTORY FORM: Figure "D":

1. PROPERTY NAME: Delhi School Teacherages

2. PROPERTY ADDRESS · Street Address: Section SE12;8N;24W
City: Delhi County: Beckham
State: OK Zip Code: 73640 Region: 7

3. PROPERTY LOCATION Lot: Township: 8N
Block or Section: Section 12SE Range: 24W

4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:

6. Identification uncertain:

7. Unable to locate:

8. Warrant further study National Register: Yes

9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: Scattered Buildings: x
Mixed use: Industrial:
Other: Rural

10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential: x
Community/Public: Military: Exploration/Settlement:
Other: Religious:

11. CONDITION OF RESOURCE Excellent: Good: x Fair: Poor:

12. ORIGINAL SITE Yes: x No: Date moved and from where:

13. ARCHITECT/BUILDER: Year Built: 1936

14. ACCESSIBLE Yes: x No:

15. PRESENT USE
Agriculture: Industry: Residential: x (type): Private
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: Religious: Other:

BUILDING CONSTRUCTION DESCRIPTION

16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:

17. FOUNDATION TYPE Stone: Brick: Concrete: x Other:

18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: Gabled: x
Other:

19. WALL CONSTRUCTION
Wood Frame: x Siding, Historic: x Present:
Masonry, bearing: Type Brick: Stone: Type:
Other, describe:

20. WINDOWS Historic, Wooden: x Metal: Present:
Window type Hung: x Single: Double: x Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:

21. DOORS Material and type. Historic: Present: x
Style: Wood: Metal: x Single: x Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE
Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: x Entry: x Full Width: x Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS
Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed:
The site has three dwellings on it and each are unique. The residence nearest the school site(#1) is owned by Fred Hildebrand; west is the second residence owned by Nolan Ford; and further west is #3 owned by Ruth Burros. See additional comment section for a description of alterations.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.
Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION
Sources of information: Field survey report and Fred Hildebrand

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7BEC3a-3f Date taken: May 21, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 13, 1987

Survey Project No: Yes: x Project Name: WPA Survey,III

30. WPA appropriation: $13,448

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: Legal description is in metes and bounds. The rural road is commonly called Farms Market Road by the local residents.

ITEM 25: Residence #1: All windows are original sash; the front door is an added feature and is a combination storm and screen; the roof-line has a gabled porch. Residence #2: All windows are original but are covered with storm and screen windows; the stoop and front porch are original features; Residence #3: The windows are original double hung but all windows are covered with storms and screens.

HISTORIC PRESERVATION SURVEY INVENTORY FORM: Figure "D":

1. PROPERTY NAME: Elk City Park (Ackley Park) Stadium

2. PROPERTY ADDRESS Street Address: 3rd Street
City: Elk City County: Beckham
State: OK Zip Code: 73644 Region: 7

3. PROPERTY LOCATION Lot: Township: 11N
Block or Section: Section 21, SW Quarter Range: 21W

4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: Object:
Structure: x Site:

6. Identification uncertain:

7. Unable to locate:

8. Warrant further study National Register: Yes

9. SITE SETTING AND FEATURES
Open Land: Commercial area: x
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:

10. HISTORIC USE

Archaeological:	Fine Arts:	Recreation: x
Agriculture:	Government:	Education:
Commercial:	Industrial:	Residential:
Community/Public: x	Military:	Exploration/Settlement:
Other:		Religious:

11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:

12. ORIGINAL SITE Yes: x No: Date moved and from where:

13. ARCHITECT/BUILDER: Year Built: 1935

14. ACCESSIBLE Yes: x No:

15. PRESENT USE

Agriculture:	Industry:	Residential:	(type):
Commercial:	Military:	Community/Public: x	
Education:	Museum:	Social/Fraternal:	
Government:	Religious:	Other: Recreation	

BUILDING CONSTRUCTION DESCRIPTION

16. NUMBER OF STORIES: Full: Partial: Below Ground:

17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:

18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: x Flat: Gabled:
Other:

19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present:
Masonry, bearing: Type Brick: Stone: Type:
Other, describe: Open sides

20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:

21. DOORS Material and type. Historic: Present:
Style: Wood: Metal: Single: Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE
Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other: Grandstand roof

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS
Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed:
The roof of the grandstand was replaced in the 1950s; all gates were added in the late 1950s.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.
Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION
Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7BEC6a-6b Date taken: May 22, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 13, 1987

Survey Project No: Yes: x Project Name: WPA Survey,III

30. WPA appropriation: $12,117

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: The grandstand is significant enough to warrant a separate field survey form.

HISTORIC PRESERVATION SURVEY INVENTORY FORM: Figure "D":

1. PROPERTY NAME: City Park Additions (Ackley Park Wall)

2. PROPERTY ADDRESS Street Address: Ackley Park Drive & 3rd Street
City: Elk City County: Beckham
State: OK Zip Code: 73644 Region: 7

3. PROPERTY LOCATION Lot: Township: 11N
Block or Section: Section 21, SW Quarter Range: 21W

4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: Object:
Structure: x Site: x

6. Identification uncertain:

7. Unable to locate:

8. Warrant further study National Register: Yes

9. SITE SETTING AND FEATURES
Open Land: Commercial area: x
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:

10. HISTORIC USE

Archaeological:	Fine Arts:	Recreation: x
Agriculture:	Government:	Education:
Commercial:	Industrial:	Residential:
Community/Public: x	Military:	Exploration/Settlement:
Other:		Religious:

11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:

12. ORIGINAL SITE Yes: x No: Date moved and from where:

13. ARCHITECT/BUILDER: Raymond Willis, Engineer Year Built: 1938

14. ACCESSIBLE Yes: x No:

15. PRESENT USE

Agriculture:	Industry:	Residential:	(type):
Commercial:	Military:	Community/Public: x	
Education:	Museum:	Social/Fraternal:	
Government:	Religious:	Other: Recreation	

BUILDING CONSTRUCTION DESCRIPTION

16. NUMBER OF STORIES: Full: Partial: Below Ground:

17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:

18. ROOFING MATERIAL Historic: Present:
Roof type Hipped: Shed: Flat: Gabled:
Other:

19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: Type Brick: Stone: x Type:
Other, describe:

20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:

21. DOORS Material and type. Historic: Present:
Style: Wood: Metal: Single: Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE
Tower: projecti_ joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS
Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed:

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.
Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION
Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7BEC7a,7b Date taken: May 22, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 13, 1987

Survey Project No: Yes: x Project Name: WPA Survey,III

30. WPA appropriation: $46,000

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS:

HISTORIC PRESERVATION SURVEY INVENTORY FORM: Figure "D":

1. PROPERTY NAME: Erick Public Elementary School

2. PROPERTY ADDRESS Street Address: Cedar and 4th Streets
City: Erick County: Beckham
State: OK Zip Code: 73645 Region: 7

3. PROPERTY LOCATION Lot: 14-19 Township: 9N
Block or Section: Block 4, Brooks Subdivision Range: 25W

4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:

6. Identification uncertain:

7. Unable to locate:

8. Warrant further study National Register: Yes

9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: x Scattered Buildings:
Mixed use: Industrial:
Other:

10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:

11. CONDITION OF RESOURCE Excellent: Good: x Fair: Poor:

12. ORIGINAL SITE Yes: x No: Date moved and from where:

13. ARCHITECT/BUILDER: Year Built: 1937

14. ACCESSIBLE Yes: x No:

15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: x Museum: Social/Fraternal:
Government: Religious: Other:

BUILDING CONSTRUCTION DESCRIPTION

16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:

17. FOUNDATION TYPE Stone: Brick: x Concrete: Other:

18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other: Barrel

19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: x Stone: Type:
Other, describe:

20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: x No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects: all are wooden paneled

21. DOORS Material and type. Historic: Present: x
Style: Glass Wood: Metal: Single: Double: x
Other, specify: Sidelights
Decorative features:

22. LARGE EXTERIOR FEATURI
Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS
Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed:
Roof over south entrance is added; awning on west side, and single metal door, and cement wall, are added features; all windows are covered with wood panelling; glass block sidelights on south end are not original equipment.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.
Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION
Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7BEC10a,10b Date taken: May 21, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 13, 1987

Survey Project No: Yes: x Project Name: WPA Surve,III

30. WPA appropriation: $22,000

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: Only the gymnasium portion of the project still remains, but the foundation for the classroom building is still in place.

HISTORIC PRESERVATION SURVEY INVENTORY FORM: Figure "D":

1. PROPERTY NAME: Sayre Agricultural Building

2. PROPERTY ADDRESS Street Address: 114 E. Enterprise Ave
City: Sayre County: Beckham
State: OK Zip Code: 73662 Region: 7

3. PROPERTY LOCATION Lot: 13 Township: 10N
Block or Section: Block 4 Range: 23W

4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:

6. Identification uncertain:

7. Unable to locate:

8. Warrant further study National Register: Yes

9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: x Scattered Buildings:
Mixed use: Industrial:
Other:

10. HISTORIC USE

Archaeological:	Fine Arts:	Recreation:
Agriculture:	Government:	Education: x
Commercial:	Industrial:	Residential:
Community/Public:	Military:	Exploration/Settlement:
Other:		Religious:

11. CONDITION OF RESOURCE Excellent: Good: Fair: x Poor:

12. ORIGINAL SITE Yes: x No: Date moved and from where:

13. ARCHITECT/BUILDER: Year Built: 1935

14. ACCESSIBLE Yes: x No:

15. PRESENT USE

Agriculture:	Industry:	Residential:	(type):
Commercial: x	Military:	Community/Public:	
Education:	Museum:	Social/Fraternal:	
Government:	Religious:	Other: Pre-school	

BUILDING CONSTRUCTION DESCRIPTION

16. NUMBER OF STORIES: 1 Full: Partial: Below Ground:

17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:

18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other:

19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: Stone: x Type: Sandstone
Other, describe:

20. WINDOWS Historic, Wooden: Metal: x Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: x Sliding: Fixed: x Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:

21. DOORS Material and type. Historic: Present: x
Style: Wood: Metal: x Single: x Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATUR
Tower: projecting. joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: x Full Width: Wrap-around: Other: Stoop
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS
Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed:
The opening that accommodated hangar doors are bricked in and a single, metal door is in place. All windows, except one, are boarded on south and north sides.The cement block addition on east side is not original. The south stoop is carpeted. The garage door opening on east side has a metal overhead door in place.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.
Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION
Sources of information: Field survey report and Sayre School Administration Office

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7BEC14a,14b Date taken: May 21, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 13, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: $9,661

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS:

HISTORIC PRESERVATION SURVEY INVENTORY FORM: Figure "D":

1. PROPERTY NAME: Sayre Recreation Facilities (Bathhouse)

2. PROPERTY ADDRESS Street Address: Section 4NW;9N;23W
City: Sayre (vic) County: Beckham
State: OK Zip Code: 73662 Region: 7

3. PROPERTY LOCATION Lot: Township: 9N
Block or Section: Section 4NW quatrant Range: 23W

4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: Object:
Structure: x Site:

6. Identification uncertain:

7. Unable to locate:

8. Warrant further study National Register: Yes

9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings: x
Mixed use: Industrial:
Other:

10. HISTORIC USE

Archaeological:	Fine Arts:	Recreation: x
Agriculture:	Government:	Education:
Commercial:	Industrial:	Residential:
Community/Public: x	Military:	Exploration/Settlement:
Other:		Religious:

11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:

12. ORIGINAL SITE Yes: x No: Date moved and from where:

13. ARCHITECT/BUILDER: Year Built: 1939

14. ACCESSIBLE Yes: x No:

15. PRESENT USE

Agriculture:	Industry:	Residential:	(type):
Commercial:	Military:	Community/Public: x	
Education:	Museum:	Social/Fraternal:	
Government:	Religious:	Other: Recreation	

BUILDING CONSTRUCTION DESCRIPTION

16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:

17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:

18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other:

19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: Stone: x Type: Red sandstone
Other, describe:

20. WINDOWS Historic, Wooden: Metal: Present: x
Window type Hung: x Single: Double: x Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:

21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: x Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE
Tower: x projecting x joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: x Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe: The tower is wrapped with spiral staircase.

24. UNATTACHED, SMALL OUTBUILDINGS
Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed:
Chain link fence is an added feature.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.
Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION
Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7BEC17a-17c Date taken: May 21, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 13, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: $89,456

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: The appropriation amount covered all the structures in the park area. They are included in a separate report.

HISTORIC PRESERVATION SURVEY INVENTORY FORM: Figure "D":

1. PROPERTY NAME: Sweetwater Public School

2. PROPERTY ADDRESS Street Address: Section 26NE;11N;26W
City: Sweetwater County: Beckham
State: OK Zip Code: 73666 Region: 7

3. PROPERTY LOCATION Lot: Township: 11N
Block or Section: Section 26NE Range: 26W

4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: x Site:

6. Identification uncertain:

7. Unable to locate:

8. Warrant further study National Register: Yes

9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:

10. HISTORIC USE

Archaeological:	Fine Arts:	Recreation:
Agriculture:	Government:	Education: x
Commercial:	Industrial:	Residential:
Community/Public:	Military:	Exploration/Settlement:
Other:		Religious:

11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:

12. ORIGINAL SITE Yes: x No: Date moved and from where:

13. ARCHITECT/BUILDER: Year Built: 1938

14. ACCESSIBLE Yes: x No:

15. PRESENT USE

Agriculture:	Industry:	Residential:	(type):
Commercial:	Military:	Community/Public:	
Education: x	Museum:	Social/Fraternal:	
Government:	Religious:	Other:	

BUILDING CONSTRUCTION DESCRIPTION

16. NUMBER OF STORIES: 1 Full: Partial: Below Ground:

17. FOUNDATION TYPE Stone: Brick: x Concrete: Other:

18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other:

19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: x Stone: Type:
Other, describe:

20. WINDOWS Historic, Wooden: Metal: Present: x
Window type Hung: x Single: Double: x Triple:
Transoms Yes: x No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:

21. DOORS Material and type. Historic: Present: x
Style: Glass Wood: Metal: Single: Double: x
Other, specify:
Decorative features: Sidelights

22. LARGE EXTERIOR FEATURE
Tower: projecti _ joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS
Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed:
All windows have been replaced with aluminum casements; original door openings have been altered to accomodate new doors; the windows on the west side are boarded 2/3.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.
Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION
Sources of information: Field survey report and the school secretary.

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: &BEC18a-18f Date taken: May 20, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 13, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: $35,339

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: Included in this report are a coal house, a storm cellar, and a classroom adition as well as the original school project.

HISTORIC PRESERVATION SURVEY INVENTORY FORM: Figure "D":

1. PROPERTY NAME: Merrit School Gymnasium

2. PROPERTY ADDRESS Street Address: Section 36SE;11N;22W
City: Elk City (vic) County: Beckham
State: OK Zip Code: 73644 Region: 7

3. PROPERTY LOCATION Lot: Township: 11N
Block or Section: Section 36SE Range: 22W

4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:

6. Identification uncertain:

7. Unable to locate:

8. Warrant further study National Register: Yes

9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings: x
Mixed use: Industrial:
Other:

10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:

11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:

12. ORIGINAL SITE Yes: x No: Date moved and from where:

13. ARCHITECT/BUILDER: Year Built: 1941

14. ACCESSIBLE Yes: x No:

15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: x Museum: Social/Fraternal:
Government: Religious: Other:

BUILDING CONSTRUCTION DESCRIPTION

16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:

17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:

18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: Gabled:
Other: Barrel

19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: Stone: x Type: Sandstone
Other, describe:

20. WINDOWS Historic, Wooden: Metal: x Present:
Window type Hung: x Single: Double: x Triple:
Transoms Yes: x No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:

21. DOORS Material and type. Historic: Present: x
Style: Glass Panel Wood: Metal: Single: Double: x
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE
Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: x Full Width: Wrap-around: Other: Stoop
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS
Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed:
Original windows have been removed and openings boarded with exception of upper portion of the wall; the four windows in the front are aluminum and are not original equipment; the front doors added in the 1960s.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.
Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION
Sources of information: Field survey report and Royce Thompson, Principal.

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7BEC13a-13d Date taken: May 22, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 13, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: $33,129

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: The classroom built in 1941 no longer exists. White composition block addition at north end of Gym (rear) was added in 1962.

HISTORIC PRESERVATION SURVEY INVENTORY FORM: Figure "D":

1. PROPERTY NAME: Home Economics Building

2. PROPERTY ADDRESS Street Address: Section 34SE;19N;22W
City: Carter (vic) County: Beckham
State: OK Zip Code: 73627 Region: 7

3. PROPERTY LOCATION Lot: Township: 19N
Block or Section: Section 34SE Range: 22W

4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:

6. Identification uncertain:

7. Unable to locate:

8. Warrant further study National Register: x

9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:

10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:

11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:

12. ORIGINAL SITE Yes: x No: Date moved and from where:

13. ARCHITECT/BUILDER: Year Built: 1938

14. ACCESSIBLE Yes: x No:

15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: x Museum: Social/Fraternal:
Government: Religious: Other:

BUILDING CONSTRUCTION DESCRIPTION

16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:

17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:

18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: Gabled: x
Other:

19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: Stone: x Type: Sandstone
Other, describe:

20. WINDOWS Historic, Wooden: x Metal: Present:
Window type Hung: x Single: Double: x Triple:
Transoms Yes: x No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:

21. DOORS Material and type. Historic: Present: x
Style: Wood: Metal: x Single: x Double:
Other, specify:
Decorative features: Sidelights

22. LARGE EXTERIOR FEATURES
Tower: projectir joined: other:
Entries: Pediments: Porte Cochere: Other:
Porches: x Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: x Gables:
Verandas: Chimneys: x placement/material: end wall, matching stone
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS
Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed:
The roof is not original material; the transom opening has been blocked in.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.
Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION
Sources of information: Field survey report and Principal Vernon Green

Photographs. MUST DE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7BEC19a,19b. Date taken: May 22, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 14, 1987

Survey Project No: Yes: x Project Name: WPA Survey, Ill

30. WPA appropriation: $10,705

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: Included in this project was a wall that was constructed along the front perimeter.

INVENTORY OF WPA RESOURCES NOT SUITABLE FOR NATIONAL REGISTER

BECKHAM COUNTY

(Region 7)

	Property Name	Location	Town	Photo Ref.
1.	Delhi School	T8N, R24W, SE12	Delhi	7BEC2a-c
2.	School Truck Shed	T8N, R24W, SE12	Delhi	7BEC4a,b
3.	City Park Pavilion	3rd and Pioneer	Elk City	7BEC8a
4.	School Addn.	Oliver and B	Elk City	7BEC9a-c
6.	High School Gym	400 S. Oak	Erick	7BEC11a,b
7.	Court House Addn.	100 S. 3rd	Sayre	7BEC15a-c
8.	City Park	T9N, R23W, NW4	Sayre	7BEC17d-f
9.	Recreation Stadium	T11N, R24W, SW23	Sayre	7BEC16a,b
10.	Dabney School	T8N, R26W, SW23	Erick vic	7BEC1a,b
11.	Hext School	T9N, R24W, SE17	Leedey vic	7BEC12a-d

NOT ON LIST, BUT INCLUDED IN FILES:

Dorey Public School — Sayre Vic

HISTORIC PRESERVATION SURVEY INVENTORY FORM: Figure "D":

1. PROPERTY NAME: Delhi Public School

2. PROPERTY ADDRESS Street Address: Section 12SE;8N;24W
City: Delhi County: Beckam
State: OK Zip Code: 73640 Region: 7

3. PROPERTY LOCATION Lot: Township: 12SE
Block or Section: 8N Range: 24W

4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:

6. Identification uncertain:

7. Unable to locate:

8. Warrant further study National Register: NO

9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings: x
Mixed use: Industrial:
Other:

10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:

11. CONDITION OF RESOURCE Excellent: Good: Fair: Poor: x

12. ORIGINAL SITE Yes: x No: Date moved and from where:

13. ARCHITECT/BUILDER: Year Built: 1939

14. ACCESSIBLE Yes: x No:

15. PRESENT USE
Agriculture: Industry: Residential: x (type): Private
Commercial: x Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: Religious: Other:

BUILDING CONSTRUCTION DESCRIPTION

16. NUMBER OF STORIES: 2 Full: x Partial: Below Ground:

17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:

18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other: Barrel

19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: Stone: Type: Natural
Other, describe:

20. WINDOWS Historic, Wooden: x Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: x Sliding: Fixed: x Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:

21. DOORS Material and type. Historic: Present: x
Style: Wood: Metal: x Single: x Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE
Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS
Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed:
Windows on the gym have been boarded up; south end of the original school is now a private residence; the gym has been used as a restaurant and the front door is an added feature.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.
Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION
Sources of information: Field survey report and Mrs. Stan Perkins

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7BEC2a-2c Date taken: May 21, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 13, 1987

Survey Project No: Yes: x Project Name: WPA Survey,III

30. WPA appropriation: $59,536

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: The property is presently owned by Mr. Stan Perkins and has been partially razed or destroyed. Its historical integrity is gone.

HISTORIC PRESERVATION SURVEY INVENTORY FORM: Figure "D":

1. PROPERTY NAME: Delhi School Truck Shed

2. PROPERTY ADDRESS Street Address: Section SE12
City: Delhi County: Beckham
State: OK Zip Code: 73640 Region: 7

3. PROPERTY LOCATION Lot: Township: 8N
Block or Section: Section 12SE Range: 24W

4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:

6. Identification uncertain:

7. Unable to locate:

8. Warrant further study National Register: No

9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: Scattered Buildings: x
Mixed use: Industrial:
Other:

10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:

11. CONDITION OF RESOURCE Excellent: Good: Fair: Poor: x

12. ORIGINAL SITE Yes: x No: Date moved and from where:

13. ARCHITECT/BUILDER: Year Built: 1940

14. ACCESSIBLE Yes: x No:

15. PRESENT USE
Agriculture: Industry: Residential: x (type): Privately used
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: Religious: Other: Farm equipment barn

BUILDING CONSTRUCTION DESCRIPTION

16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:

17. FOUNDATION TYPE Stone: Brick: x Concrete: Other:

18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: x Shed: Flat: Gabled:
Other:

19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: x Stone: Type:
Other, describe:

20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:

21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: Double: x
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE
Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS
Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed:
All windows have been covered with corrugated tin; the double door may be original; transom opening is evident but has been left empty of glass or other material.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.
Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION
Sources of information: Field Survey Report and Jack Turner

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7BEC4a,4b Date taken: May 21, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 13, 1987

Survey Project No: Yes: x Project Name: WPA Survey,III

30. WPA appropriation: $31,147

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: The building is not complete evidence of the project covered by the appropriation. The site is presently owned by Jack Turner. The owner has destroyed the historical integrity of the structure and it cannot warrant further study.

HISTORIC PRESERVATION SURVEY INVENTORY FORM: Figure "D":

1. PROPERTY NAME: Elk City Park (Picnic Pavillion)

2. PROPERTY ADDRESS Street Address: 3rd Street and Pioneer Road
City: Elk City County: Beckham
State: OK Zip Code: 73644 Region: 7

3. PROPERTY LOCATION Lot: Township: 11N
Block or Section: Section 21,NW Quarter Range: 21W

4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: Object:
Structure: x Site:

6. Identification uncertain:

7. Unable to locate:

8. Warrant further study National Register: No

9. SITE SETTING AND FEATURES
Open Land: Commercial area: x
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:

10. HISTORIC USE

Archaeological:	Fine Arts:	Recreation: x
Agriculture:	Government:	Education:
Commercial:	Industrial:	Residential:
Community/Public: x	Military:	Exploration/Settlement:
Other:		Religious:

11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:

12. ORIGINAL SITE Yes: x No: Date moved and from where:

13. ARCHITECT/BUILDER: Year Built: 1940

14. ACCESSIBLE Yes: x No:

15. PRESENT USE

Agriculture:	Industry:	Residential:	(type):
Commercial:	Military:	Community/Public: x	
Education:	Museum:	Social/Fraternal:	
Government:	Religious:	Other: Recreation	

BUILDING CONSTRUCTION DESCRIPTION

16. NUMBER OF STORIES: Full: Partial: Below Ground:

17. FOUNDATION TYPE Stone: Brick: Concrete: Other:

18. ROOFING MATERIAL Historic: Present:
Roof type Hipped: Shed: Flat: Gabled:
Other:

19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present:
Masonry, bearing: Type Brick: Stone: Type:
Other, describe:

20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:

21. DOORS Material and type. Historic: Present:
Style: Wood: Metal: Single: Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE
Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS
Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed:

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.
Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION
Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7BEC8a Date taken: May 22, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 13, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: $20,270

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: The only remnant of WPA are a few picnic tables. They are constructed of stone, concrete slab tops, and wooden seats.

HISTORIC PRESERVATION SURVEY INVENTORY FORM: Figure "D":

1. PROPERTY NAME: Elk City School Addition

2. PROPERTY ADDRESS Street Address: Oliver and B Streets
City: Elk City County: Beckham
State: OK Zip Code: 73644 Region: 7

3. PROPERTY LOCATION Lot: city tract Township: 11N
Block or Section: Section 21 NW Range: 21W

4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:

6. Identification uncertain:

7. Unable to locate:

8. Warrant further study National Register: No

9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: x Scattered Buildings:
Mixed use: Industrial:
Other:

10. HISTORIC USE

Archaeological:	Fine Arts:	Recreation:
Agriculture:	Government:	Education: x
Commercial:	Industrial:	Residential:
Community/Public:	Military:	Exploration/Settlement:
Other:		Religious:

11. CONDITION OF RESOURCE Excellent: Good: x Fair: Poor:

12. ORIGINAL SITE Yes: x No: Date moved and from where:

13. ARCHITECT/BUILDER: Year Built: 1939

14. ACCESSIBLE Yes: x No:

15. PRESENT USE

Agriculture:	Industry:	Residential:	(type):
Commercial:	Military:	Community/Public:	
Education: x	Museum:	Social/Fraternal:	
Government:	Religious:	Other:	

BUILDING CONSTRUCTION DESCRIPTION

16. NUMBER OF STORIES: 1 Full: Partial: Below Ground:

17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:

18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other:

19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: x Stone: x Type: Sandstone
Other, describe:

20. WINDOWS Historic, Wooden: Metal: Present: x
Window type Hung: x Single: Double: x Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:

21. DOORS Material and type. Historic: Present: x
Style: Glass panel Wood: Metal: Single: x Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE
Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS
Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed: Brick on upper half of facade replaced wood siding; all doors are added equipment; brick addition on east side is not a part of the original construction project.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.
Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION
Sources of information: Field survey report and Lawson Walker, maintenance supervisor

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7BEC9a-9c Date taken: June 17, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 13, 1987

Survey Project No: Yes: x Project Name: WPA Survey,III

30. WPA appropriation: $3,654

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: According to information gathered at the Elk City Board of Education office, this building and walled in grounds was originally constructed as a park office building where the Park Superintendent had his office. No records or documents could be found to substantiate this information.

HISTORIC PRESERVATION SURVEY INVENTORY FORM: Figure "D":

1. PROPERTY NAME: Erick Public High School Gym and Addition

2. PROPERTY ADDRESS Street Address: 400 South Oak
City: Erick County: Beckham
State: OK Zip Code: 73645 Region: 7

3. PROPERTY LOCATION Lot: unknown Township: 9N
Block or Section: Block 2, Minton Addition Range: 25W

4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:

6. Identification uncertain:

7. Unable to locate:

8. Warrant further study National Register: No

9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: x Scattered Buildings: x
Mixed use: Industrial:
Other:

10. HISTORIC USE

Archaeological:	Fine Arts:	Recreation:
Agriculture:	Government:	Education: x
Commercial:	Industrial:	Residential:
Community/Public:	Military:	Exploration/Settlement:
Other:		Religious:

11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:

12. ORIGINAL SITE Yes: x No: Date moved and from where:

13. ARCHITECT/BUILDER: Year Built: 1939

14. ACCESSIBLE Yes: x No:

15. PRESENT USE

Agriculture:	Industry:	Residential:	(type):
Commercial:	Military:	Community/Public:	
Education: x	Museum:	Social/Fraternal:	
Government:	Religious:	Other:	

BUILDING CONSTRUCTION DESCRIPTION

16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:

17. FOUNDATION TYPE Stone: Brick: x Concrete: Other:

18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other: Barrel

19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: x Stone: Type:
Other, describe:

20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:

21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: x Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE
Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS
Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed:
All windows on the side walls have been bricked in; original front entrance obscured by an addition. At the rear of the gym are classrooms, two windows and a door entrance remain.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.
Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION
Sources of information: Field survey report and Richard Deeds, Superintendent of the school.

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7BEC11a,11b Date taken: May 21, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 31, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: $60,693

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: Massive alterations have disqualified this building for further study.

HISTORIC PRESERVATION SURVEY INVENTORY FORM: Figure "D":

1. PROPERTY NAME: Beckham County Court House Addition

2. PROPERTY ADDRESS Street Address: 100 South 3rd
City: Sayre County: Beckham
State: OK Zip Code: 73662 Region: 7

3. PROPERTY LOCATION Lot: 1-24 Township: 11N
Block or Section: Bloc 4 Range: 24W

4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:

6. Identification uncertain:

7. Unable to locate:

8. Warrant further study National Register: No

9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: Scattered Buildings:
Mixed use: x Industrial:
Other:

10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: x Education:
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:

11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:

12. ORIGINAL SITE Yes: x No: Date moved and from where:

13. ARCHITECT/BUILDER: Year Built: 1935

14. ACCESSIBLE Yes: x No:

15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: x Religious: Other:

BUILDING CONSTRUCTION DESCRIPTION

16. NUMBER OF STORIES: 3 Full: 2 Partial: Below Ground: 1

17. FOUNDATION TYPE Stone: Brick: x Concrete: Other:

18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other:

19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: Stone: Type: Stucco
Other, describe:

20. WINDOWS Historic, Wooden: Metal: x Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: x No:
Casement: x Sliding: Fixed: x Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:

21. DOORS Material and type. Historic: Present: x
Style: Wood: Metal: x Single: Double: x
Other, specify:
Decorative features: Sidelights

22. LARGE EXTERIOR FEATURE
Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: x Other:
Porches: Entry: x Full Width: Wrap-around: Other: Stoop
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe: the addition has the same peg-style molding as the original structure. The peg motif is made with the same material as the walls.

24. UNATTACHED, SMALL OUTBUILDINGS
Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed:
Doors on the west end are additional equipment; all windows have been covered with combination storm and screens. The sides of the portico have been covered with aluminum windshields.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.
Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION
Sources of information: Field survey report and Deputy Risenhoover

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7BEC15a-15c Date taken: May 21, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 13, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: $57,183

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: The portico and stoop are original features. The building now houses the Beckham County Sheriff's Office but was the County Jail until 1964 when a new jail facility was constructed.

HISTORIC PRESERVATION SURVEY INVENTORY FORM: Figure "D":

1. PROPERTY NAME: Sayre City Park

2. PROPERTY ADDRESS Street Address: Section 4NW;9N;23W
City: Sayre County: Beckham
State: OK Zip Code: 73662 Region: 7

3. PROPERTY LOCATION Lot: Township: 9N
Block or Section: Section 4, NW quatrant Range: 23W

4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: Object:
Structure: x Site:

6. Identification uncertain:

7. Unable to locate:

8. Warrant further study National Register: No

9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings: x
Mixed use: Industrial:
Other:

10. HISTORIC USE
Archaeological: Fine Arts: Recreation: x
Agriculture: Government: Education:
Commercial: Industrial: Residential:
Community/Public: x Military: Exploration/Settlement:
Other: Religious:

11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:

12. ORIGINAL SITE Yes: x No: Date moved and from where:

13. ARCHITECT/BUILDER: Year Built: 1939

14. ACCESSIBLE Yes: x No:

15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public: x
Education: Museum: Social/Fraternal:
Government: Religious: Other: Recreation

BUILDING CONSTRUCTION DESCRIPTION

16. NUMBER OF STORIES: Full: Partial: Below Ground:

17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:

18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: Gabled:
Other: Parasol style

19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present:
Masonry, bearing: Type Brick: Stone: Type:
Other, describe:

20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:

21. DOORS Material and type. Historic: Present:
Style: Wood: Metal: Single: Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATUR
Tower: projecti joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS
Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed:

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.
Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION
Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7BEC17d-17f Date taken: May 21, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 13, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: unknown

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: The structure included in this report are the Pavillion, the pump and heater housing, and the wall along the outside rim of the park.

HISTORIC PRESERVATION SURVEY INVENTORY FORM: Figure "D":

1. PROPERTY NAME: Sayre Recreation Stadium

2. PROPERTY ADDRESS Street Address: Section 23SW;11N;24W
City: Sayre County: Beckham
State: OK Zip Code: 73662 Region: 7

3. PROPERTY LOCATION Lot: 1-19 Township: 11N
Block or Section: Block 2,Court House Addition Range: 24W

4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: Object:
Structure: x Site: x

6. Identification uncertain: x (see additional comments)

7. Unable to locate:

8. Warrant further study National Register: NO

9. SITE SETTING AND FEATURES
Open Land: Commercial area: x
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:

10. HISTORIC USE
Archaeological: Fine Arts: Recreation: x
Agriculture: Government: Education:
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:

11. CONDITION OF RESOURCE Excellent: Good: x Fair: Poor:

12. ORIGINAL SITE Yes: x No: Date moved and from where:

13. ARCHITECT/BUILDER: Year Built: unknown

14. ACCESSIBLE Yes: x No:

15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public: x
Education: Museum: Social/Fraternal:
Government: Religious: Other: Recreation

BUILDING CONSTRUCTION DESCRIPTION

16. NUMBER OF STORIES: Full: Partial: Below Ground:

17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:

18. ROOFING MATERIAL Historic: Present:
Roof type Hipped: Shed: Flat: Gabled:
Other:

19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present:
Masonry, bearing: Type Brick: Stone: Type:
Other, describe:

20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:

21. DOORS Material and type. Historic: Present:
Style: Wood: Metal: Single: Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE
Tower: projecting. joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other: Aluminum Press Box

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS
Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed:

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.
Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION
Sources of information: Field survey. There was no report of this structure but it does look as if it may be WPA work.

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7BEC16a,16b Date taken: June 17, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 13, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: unknown

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: The press box is an addition. This structure was surveyed because it may be a WPA project.

HISTORIC PRESERVATION SURVEY INVENTORY FORM: Figure "D":

1. PROPERTY NAME: Dabney Public School

2. PROPERTY ADDRESS Street Address: Section 23SW;8N;26W
City: Erick (vic) County: Beckam
State: OK Zip Code: 73645 Region: 7

3. PROPERTY LOCATION Lot: Township: 8N
Block or Section: Section 23SW Range: 26W

4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:

6. Identification uncertain:

7. Unable to locate:

8. Warrant further study National Register: No

9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:

10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:

11. CONDITION OF RESOURCE Excellent: Good: Fair: Poor: x

12. ORIGINAL SITE Yes: x No: Date moved and from where:

13. ARCHITECT/BUILDER: Year Built: 1938

14. ACCESSIBLE Yes: No: x

15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: Religious: Other: Abandoned

BUILDING CONSTRUCTION DESCRIPTION

16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:

17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:

18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: x Shed: Flat: Gabled:
Other:

19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: Stone: x Type: Sandstone
Other, describe:

20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:

21. DOORS Material and type. Historic: x Present:
Style: Wood: x Metal: Single: Double: x
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE
Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: x Entry: x Full Width: x Wrap-around: Other: Stoop
Stairs: Balconies: Dormers: x Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS
Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other: Privy

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed:
All windows are gone; only the front door is still in place.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.
Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION
Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7BEC1a,1b Date taken: May 21, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 13, 1987

Survey Project No: Yes: x Project Name: WPA Survey,III

30. WPA appropriation: $6,730

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: The building is in advanced stages of deterioration and cannot qualify for further study.

HISTORIC PRESERVATION SURVEY INVENTORY FORM: Figure "D":

1. PROPERTY NAME: Hext Public School

2. PROPERTY ADDRESS Street Address: Section17SE;9N;24W
City: Leedey (vic) County: Beckham
State: OK Zip Code: 73654 Region: 7

3. PROPERTY LOCATION Lot: Township: 9N
Block or Section: Section 17SE Range: 24W

4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:

6. Identification uncertain:

7. Unable to locate:

8. Warrant further study National Register: No

9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:

10. HISTORIC USE

Archaeological:	Fine Arts:	Recreation:
Agriculture:	Government:	Education: x
Commercial:	Industrial:	Residential:
Community/Public:	Military:	Exploration/Settlement:
Other:		Religious:

11. CONDITION OF RESOURCE Excellent: Good: Fair: Poor: x

12. ORIGINAL SITE Yes: x No: Date moved and from where:

13. ARCHITECT/BUILDER: Year Built: 1937

14. ACCESSIBLE Yes: No: x

15. PRESENT USE

Agriculture:	Industry:	Residential:	(type):
Commercial:	Military:	Community/Public:	
Education:	Museum:	Social/Fraternal:	
Government:	Religious:	Other: Abandoned	

BUILDING CONSTRUCTION DESCRIPTION

16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:

17. FOUNDATION TYPE Stone: Brick: x Concrete: Other:

18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: Gabled:
Other: Barrel

19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: x Stone: Type:
Other, describe:

20. WINDOWS Historic, Wooden: Metal: x Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: x Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:

21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: Double: x
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE
Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: x Full Width: Wrap-around: Other: Stoop
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS
Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed:
The sliding metal doors are not original equipment; all windows are covered with makeshift wood-frame screens; barbed wire is not original equipment.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.
Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION
Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7BEC12a-12d Date taken: May 21, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 13, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: $25,582

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: The extensive deterioration of the building disqualifies it for further study.

HISTORIC PRESERVATION SURVEY INVENTORY FORM: Figure "D":

1. PROPERTY NAME: Doxey Public School

2. PROPERTY ADDRESS Street Address: Section 13NE;10N;23W
City: Sayre (vic) County: Beckham
State: OK Zip Code: 73662 Region: 7

3. PROPERTY LOCATION Lot: Township: 10N
Block or Section: Section 13NE Range: 23W

4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: x Site:

6. Identification uncertain:

7. Unable to locate: x

8. Warrant further study National Register:

9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: x Scattered Buildings: x
Mixed use: Industrial:
Other:

10. HISTORIC USE

Archaeological:	Fine Arts:	Recreation:
Agriculture:	Government:	Education: x
Commercial:	Industrial:	Residential:
Community/Public:	Military:	Exploration/Settlement:
Other:		Religious:

11. CONDITION OF RESOURCE Excellent: Good: Fair: x Poor:

12. ORIGINAL SITE Yes: x No: Date moved and from where:

13. ARCHITECT/BUILDER: Year Built: 1935

14. ACCESSIBLE Yes: x No:

15. PRESENT USE

Agriculture:	Industry:	Residential: x	(type): Private
Commercial:	Military:	Community/Public:	
Education:	Museum:	Social/Fraternal:	
Government:	Religious:	Other:	

BUILDING CONSTRUCTION DESCRIPTION

16. NUMBER OF STORIES: Full: Partial: Below Ground:

17. FOUNDATION TYPE Stone: Brick: Concrete: Other:

18. ROOFING MATERIAL Historic: Present:
Roof type Hipped: Shed: Flat: Gabled:
Other:

19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present:
Masonry, bearing: Type Brick: Stone: Type:
Other, describe:

20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:

21. DOORS Material and type. Historic: Present:
Style: Wood: Metal: Single: Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE
Tower: projecting. joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS
Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other: Cistern, privy, and the foundation of the coal house

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed:

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.
Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION
Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7BEC5a-5c Date taken: May 22, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 13, 1987

Survey Project No: Yes: x Project Name: WPA Survey,III

30. WPA appropriation: $37,320

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: A storm cellar is on the site but was not a part of this project. The property is presently owned by Bobby Martin. The privy and cistern as well as the wall in front are included in the photographs.