WPA RESOURCES WARRANTING FURTHER STUDY FOR NATIONAL REGISTER

TILLMAN COUNTY

(Region 7)

	Property Name	Location	Town	Photo Ref.
1.	County Garage	620 S. 8th Street	Frederick	7TIL1a,b
2.	Junior High School	100 S. 12th St.	Frederick	7TIL2a,b
3.	City Pool & Bathhouse	200 S 17th St.	Frederick	7TIL3a,b
4.	Stadium	Diamond Street	Frederick	7TIL4a,b
5.	City Hall	223 S. Main	Granfield	7TIL5a,b
6.	Community Bldg.	Taylor and First	Granfield	7TIL6a,b
7.	School Voc. Ed. Bldg.	112 S. Broadway	Tipton	7TIL7a,b
8.	Tennis Courts	112 S. Broadway	Tipton	7TIL8a
9.	Teacherage	112 S. Broadway	Tipton	7TIL9a,b

HISTORIC PRESERVATION SURVEY INVENTORY FORM Figure "D"


1. PROPERTY NAME: Tillman County Garage

2. PROPERTY ADDRESS Street Address: 620 S. 8th
City: Frederick County: Tillman
State: OK Zip Code: 73542 Region: 7

3. PROPERTY LOCATION Lot: 16,17,18 Township:
Block or Section: 8, Stout's South Addition Range:

4. PROPERTY TYPE (Category)
Building: x Object:
Structure: Site:

5. PLACEMENT ON BLOCK or MAP



6. Identification uncertain:

7. Unable to locate:

8. Warrant further study National Register: yes

9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: Scattered Buildings:
Mixed use: x Industrial:
Other:

10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: x Education:
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:

11. CONDITION OF RESOURCE Excellent: Good: x Fair: Poor:

12. ORIGINAL SITE Yes: x No: Date moved and from where:

13. ARCHITECT/BUILDER: Year Built: 1936-37

14. ACCESSIBLE Yes: x No:

15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: x Religious: Other:

BUILDING CONSTRUCTION DESCRIPTION

16. NUMBER OF STORIES: 1 Full: 1 Partial: Below Ground:

17. FOUNDATION TYPE Stone: Brick: Concrete: x Other:

18. ROOFING MATERIAL Historic: Present: composition
Roof type Hipped: Shed: Flat: x Gabled:
Other:

19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present: x
Masonry, bearing: x Type Brick: Stone: Type:
Other, describe: poured concrete block

20. WINDOWS Historic, Wooden: Metal: Present: x
Window type Hung: Single: Double: Triple:
Transoms Yes: No: x
Casement: x Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:

21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: x Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURES
Tower: projecti joined: other:
Entries: Pediment Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe: parapets.

24. UNATTACHED, SMALL OUTBUILDINGS
Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed: Tin addition to east end.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.
Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION
Sources of information: field survey

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7TIL1a,1b Date taken: 05/26/87 Photographer: Barry Thorne

29. NAME OF PREPARER: Barry Thorne DATE: 07/15/87

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: $5,912

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS:

HISTORIC PRESERVATION SURVEY INVENTORY FORM Figure "D"


1. PROPERTY NAME: Frederick Junior High School

2. PROPERTY ADDRESS Street Address: 100 S. 12th
City: Frederick County: Tillman
State: OK Zip Code: 73542 Region: 7

3. PROPERTY LOCATION Lot: all Township:
Block or Section: 31, Frederick Original Range:

4. PROPERTY TYPE (Category)
Building: x Object:
Structure: Site:

5. PLACEMENT ON BLOCK or MAP



6. Identification uncertain:

7. Unable to locate:

8. Warrant further study National Register: yes

9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: x Scattered Buildings:
Mixed use: Industrial:
Other:

10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:

11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:

12. ORIGINAL SITE Yes: x No: Date moved and from where:

13. ARCHITECT/BUILDER: Year Built: 1937-38

14. ACCESSIBLE Yes: x No:

15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: x Museum: Social/Fraternal:
Government: Religious: Other:

BUILDING CONSTRUCTION DESCRIPTION

16. NUMBER OF STORIES: 2 Full: 2 Partial: Below Ground:

17. FOUNDATION TYPE Stone: Brick: Concrete: x Other:

18. ROOFING MATERIAL Historic: Present: composition
Roof type Hipped: Shed: Flat: x Gabled:
Other:

19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present: x
Masonry, bearing: x Type Brick: x Stone: Type:
Other, describe:

20. WINDOWS Historic, Wooden: Metal: Present: wood sash
Window type Hung: x Single: Double: x Triple:
Transoms Yes: x No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: x Bay: Other:
Glazing: Decorative aspects:

21. DOORS Material and type. Historic: Present: x
Style: glass panel Wood: Metal: Single: Double: x
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURES
Tower: projectin joined: other:
Entries: x Pediments x Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: x Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe: pilasters; parapets with concrete capping; recessed entryways.

24. UNATTACHED, SMALL OUTBUILDINGS
Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed: new glass panel doors; new aluminum windows on east and lower southeast corner; one front window used as vent.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.
Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION
Sources of information: field survey

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7TIL2a,2b Date taken: 05/25/87 Photographer: Barry Thorne

29. NAME OF PREPARER: Barry Thorne DATE: 07/15/87

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: $74,044

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS:

HISTORIC PRESERVATION SURVEY INVENTORY FORM Figure "D"


1. PROPERTY NAME: Frederick City Pool and Bathhouse

2. PROPERTY ADDRESS Street Address: 200 S. 17
City: Frederick County: Tillman
State: OK Zip Code: 73542 Region: 7

3. PROPERTY LOCATION Lot: All Township:
Block or Section: 3, Ray's 2nd Addition Range:

4. PROPERTY TYPE (Category)
Building: x Object:
Structure: Site:

5. PLACEMENT ON BLOCK or MAP



6. Identification uncertain:

7. Unable to locate:

8. Warrant further study National Register: yes

9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: x Scattered Buildings:
Mixed use: Industrial:
Other:

10. HISTORIC USE
Archaeological: Fine Arts: Recreation: x
Agriculture: Government: Education:
Commercial: Industrial: Residential:
Community/Public: x Military: Exploration/Settlement:
Other: Religious:

11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:

12. ORIGINAL SITE Yes: x No: Date moved and from where:

13. ARCHITECT/BUILDER: Year Built: 1936

14. ACCESSIBLE Yes: x No:

15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public: x
Education: Museum: Social/Fraternal:
Government: Religious: Other: recreation

BUILDING CONSTRUCTION DESCRIPTION

16. NUMBER OF STORIES: 2 Full: 1 Partial: 1 Below Ground:

17. FOUNDATION TYPE Stone: Brick: Concrete: x Other:

18. ROOFING MATERIAL Historic: Present: composition
Roof type Hipped: Shed: Flat: x Gabled:
Other:

19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present: x
Masonry, bearing: x Type Brick: Stone: Type:
Other, describe: poured concrete

20. WINDOWS Historic, Wooden: Metal: Present: x
Window type Hung: Single: Double: Triple:
Transoms Yes: No: x
Casement: Sliding: Fixed: x Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:

21. DOORS Material and type. Historic: Present: x
Style: Wood: Metal: x Single: Double: x
Other, specify:
Decorative features:

22. LARGE EXTERIOR --
Tower: projecti[illegible] joined: other:
Entries: Pediment[illegible] Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: x Balconies: x Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe: parapets; hood over front entry

24. UNATTACHED, SMALL OUTBUILDINGS
Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed: windows on upper story bricked over.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.
Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION
Sources of information: field survey

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7TIL3a,3b Date taken: 05/25/87 Photographer: Barry Thorne

29. NAME OF PREPARER: Barry Thorne DATE: 07/15/87

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: $16,995

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS:

HISTORIC PRESERVATION SURVEY INVENTORY FORM Figure "D"


1. PROPERTY NAME: Frederick Stadium

2. PROPERTY ADDRESS Street Address: S. Diamond Ave.
City: Frederick County: Tillman
State: OK Zip Code: 73542 Region: 7

3. PROPERTY LOCATION Lot: Township:
Block or Section: E 1/2 of 27, 28 Range:

4. PROPERTY TYPE (Category)
Building:
Structure: x
Object:
Site:

5. PLACEMENT ON BLOCK or MAP



6. Identification uncertain:

7. Unable to locate:

8. Warrant further study National Register: yes

9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: Scattered Buildings:
Mixed use: Industrial: x
Other:

10. HISTORIC USE
Archaeological: Fine Arts: Recreation: x
Agriculture: Government: Education:
Commercial: Industrial: Residential:
Community/Public: x Military: Exploration/Settlement:
Other: Religious:

11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:

12. ORIGINAL SITE Yes: x No: Date moved and from where:

13. ARCHITECT/BUILDER: Year Built: 1941

14. ACCESSIBLE Yes: x No:

15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public: x
Education: Museum: Social/Fraternal:
Government: Religious: Other: recreational

BUILDING CONSTRUCTION DESCRIPTION

16. NUMBER OF STORIES: Full: Partial: Below Ground:

17. FOUNDATION TYPE Stone: Brick: Concrete: Other:

18. ROOFING MATERIAL Historic: Present:
Roof type Hipped: Shed: Flat: Gabled:
Other:

19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present:
Masonry, bearing: Type Brick: Stone: Type:
Other, describe:

20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:

21. DOORS Material and type. Historic: Present:
Style: Wood: Metal: Single: Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURES
Tower: projecti joined: other:
Entries: Pediment Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS
Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed: new pressboxes on both stands.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.
Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION
Sources of information: field survey

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7TIL4a,4b Date taken: 05/25/87 Photographer: Barry Thorne

29. NAME OF PREPARER: Barry Thorne DATE: 07/16/87

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: $18,250

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS:

HISTORIC PRESERVATION SURVEY INVENTORY FORM Figure "D"


1. PROPERTY NAME: Grandfield City Hall

2. PROPERTY ADDRESS Street Address: 223 S. Main
City: Grandfield County: Tillman
State: OK Zip Code: 73546 Region: 7

3. PROPERTY LOCATION Lot: 21-24 Township:
Block or Section: 23, Grandfield Original Range:

4. PROPERTY TYPE (Category)
Building: x Object:
Structure: Site:

5. PLACEMENT ON BLOCK or MAP



6. Identification uncertain:

7. Unable to locate:

8. Warrant further study National Register: yes

9. SITE SETTING AND FEATURES
Open Land: Commercial area: x
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:

10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: x Education:
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:

11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:

12. ORIGINAL SITE Yes: x No: Date moved and from where:

13. ARCHITECT/BUILDER: Year Built: 1940

14. ACCESSIBLE Yes: x No:

15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: x Religious: Other:

BUILDING CONSTRUCTION DESCRIPTION

16. NUMBER OF STORIES: 1 Full: 1 Partial: Below Ground:

17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:

18. ROOFING MATERIAL Historic: Present: composition
Roof type Hipped: Shed: Flat: x Gabled:
Other:

19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present: x
Masonry, bearing: x Type Brick: Stone: x Type: native
Other, describe:

20. WINDOWS Historic, Wooden: Metal: Present: x
Window type Hung: Single: Double: Triple:
Transoms Yes: No: x
Casement: x Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects: cut stone sills

21. DOORS Material and type. Historic: Present: x
Style: glass panel Wood: Metal: Single: x Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURES
Tower: projecti .joined: other:
Entries: Pediment Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe: stone beltline

24. UNATTACHED, SMALL OUTBUILDINGS
Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: x No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed: new roof; new glass panel doors; windows on the east side covered with wood inserts.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.
Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION
Sources of information: field survey

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7TIL5a,5b Date taken: 05/25/87 Photographer: Barry Thorne

29. NAME OF PREPARER: Barry Thorne DATE: 07/16/87

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: $7,689

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS:


HISTORIC PRESERVATION SURVEY INVENTORY FORM Figure "D"

1. PROPERTY NAME: Grandfield Community Building

2. PROPERTY ADDRESS Street Address: N. Taylor and E. First
City: Grandfield County: Tillman
State: OK Zip Code: 73546 Region: 7

3. PROPERTY LOCATION Lot: 9-12 Township:
Block or Section: 22, Grandfield Original Range:

4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:



6. Identification uncertain:

7. Unable to locate:

8. Warrant further study National Register: yes

9. SITE SETTING AND FEATURES
Open Land: Commercial area: x
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:

10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education:
Commercial: Industrial: Residential:
Community/Public: x Military: Exploration/Settlement:
Other: Religious:

11. CONDITION OF RESOURCE Excellent: Good: Fair: x Poor:

12. ORIGINAL SITE Yes: x No: Date moved and from where:

13. ARCHITECT/BUILDER: Year Built: 1941

14. ACCESSIBLE Yes: x No:

15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public: x
Education: Museum: Social/Fraternal:
Government: Religious: Other:

BUILDING CONSTRUCTION DESCRIPTION

16. NUMBER OF STORIES: 1 Full: 1 Partial: Below Ground:

17. FOUNDATION TYPE Stone: Brick: Concrete: x Other:

18. ROOFING MATERIAL Historic: Present: composition
Roof type Hipped: x Shed: Flat: Gabled:
Other:

19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present: x
Masonry, bearing: Type Brick: Stone: Type:
Other, describe: poured concrete

20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:

21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: x Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURES
Tower: projectir joined: other:
Entries: Pediment Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe: Parapets; pilasters.

24. UNATTACHED, SMALL OUTBUILDINGS
Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed: Windows covered; tin covering portion of west wall.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.
Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION
Sources of information: field survey

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7TIL6a,6b Date taken: 05/25/87 Photographer: Barry Thorne

29. NAME OF PREPARER: Barry Thorne DATE: 07/16/87

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: $9,249

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS:

HISTORIC PRESERVATION SURVEY INVENTORY FORM Figure "D"

1. PROPERTY NAME: Tipton Sch. Voc. Bldg.

2. PROPERTY ADDRESS Street Address: 112 S. Broadway
City: Tipton County: Tillman
State: OK Zip Code: 73570 Region: 7

3. PROPERTY LOCATION Lot: all Township:
Block or Section: E, Tipton Addition Range:

4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:

6. Identification uncertain:

7. Unable to locate:

8. Warrant further study National Register: yes

9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:

10. HISTORIC USE

Archaeological:	Fine Arts:	Recreation:
Agriculture:	Government:	Education: x
Commercial:	Industrial:	Residential:
Community/Public:	Military:	Exploration/Settlement:
Other:		Religious:

11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:

12. ORIGINAL SITE Yes: x No: Date moved and from where:

13. ARCHITECT/BUILDER: Year Built: 1940

14. ACCESSIBLE Yes: x No:

15. PRESENT USE

Agriculture:	Industry:	Residential:	(type):
Commercial:	Military:	Community/Public:	
Education: x	Museum:	Social/Fraternal:	
Government:	Religious:	Other:	

BUILDING CONSTRUCTION DESCRIPTION

16. NUMBER OF STORIES: 1 Full: 1 Partial: Below Ground:

17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:

18. ROOFING MATERIAL Historic: Present: composition
Roof type Hipped: Shed: Flat: Gabled: x
Other:

19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present: x
Masonry, bearing: x Type Brick: Stone: x Type:
Other, describe:

20. WINDOWS Historic, Wooden: Metal: Present: metal sash
Window type Hung: x Single: Double: x Triple:
Transoms Yes: No: x
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:

21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: x Double: X
Other, specify: garage
Decorative features:

22. LARGE EXTERIOR FEATURES
Tower: projectir joined: other:
Entries: Pediments Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS
Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed: tin addition to the east; new brick facade on the west.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.
Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION
Sources of information: field survey

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7TIL7a,7b Date taken: 05/16/87 Photographer: Barry Thorne

29. NAME OF PREPARER: Barry Thorne DATE: 07/16/87

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: $80,445

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: Part of the allocation was also for a garage which is gone and for Tennis Courts which are documented on a separate form.

Attachment :

HISTORIC PRESERVATION SURVEY INVENTORY FORM Figure "D"

1. PROPERTY NAME: Tipton School Tennis Courts

2. PROPERTY ADDRESS Street Address: 112 S. Broadway
City: Tipton County: Tillman
State: OK Zip Code: 73570 Region: 7

3. PROPERTY LOCATION Lot: all Township:
Block or Section: E, Tipton Addition Range:

4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: Object: x
Structure: Site:

6. Identification uncertain: x

7. Unable to locate:

8. Warrant further study National Register: yes

9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:

10. HISTORIC USE
Archaeological: Fine Arts: Recreation: x
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:

11. CONDITION OF RESOURCE Excellent: Good: x Fair: Poor:

12. ORIGINAL SITE Yes: x No: Date moved and from where:

13. ARCHITECT/BUILDER: Year Built: 1940

14. ACCESSIBLE Yes: x No:

15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: x Museum: Social/Fraternal:
Government: Religious: Other:

BUILDING CONSTRUCTION DESCRIPTION

16. NUMBER OF STORIES: Full: Partial: Below Ground:

17. FOUNDATION TYPE Stone: Brick: Concrete: Other:

18. ROOFING MATERIAL Historic: Present:
Roof type Hipped: Shed: Flat: Gabled:
Other:

19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present:
Masonry, bearing: Type Brick: Stone: Type:
Other, describe:

20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:

21. DOORS Material and type. Historic: Present:
Style: Wood: Metal: Single: Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURES
Tower: projecti joined: other:
Entries: Pediment Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS
Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed:

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.
Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION
Sources of information: field survey

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7TIL8a Date taken: 05/25/87 Photographer: Barry Thorne

29. NAME OF PREPARER: Barry Thorne DATE: 07/16/87

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: $80,445

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: A garage and a vocational building were also part of the allocation.

HISTORIC PRESERVATION SURVEY INVENTORY FORM Figure "D"

1. PROPERTY NAME: Tipton School Teacherage

2. PROPERTY ADDRESS Street Address: 112 S. Broadway
City: Tipton County: Tillman
State: OK Zip Code: 73570 Region: 7

3. PROPERTY LOCATION Lot: all Township:
Block or Section: E, Tipton Addition Range:

4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:

6. Identification uncertain: x

7. Unable to locate:

8. Warrant further study National Register: yes

9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:

10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:

11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:

12. ORIGINAL SITE Yes: x No: Date moved and from where:

13. ARCHITECT/BUILDER: Year Built: 1938

14. ACCESSIBLE Yes: x No:

15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: x Museum: Social/Fraternal:
Government: Religious: Other:

BUILDING CONSTRUCTION DESCRIPTION

16. NUMBER OF STORIES: 1 Full: 1 Partial: Below Ground:

17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:

18. ROOFING MATERIAL Historic: Present: composition
Roof type Hipped: Shed: Flat: Gabled: x
Other:

19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present: x
Masonry, bearing: x Type Brick: Stone: x Type: native
Other, describe:

20. WINDOWS Historic, Wooden: Metal: Present: wood sash
Window type Hung: x Single: Double: x Triple:
Transoms Yes: No: x
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:

21. DOORS Material and type. Historic: Present: x
Style: glass panel Wood: Metal: Single: Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURES
Tower: projecti joined: other:
Entries: Pediment Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: x placement/material: endwall/stone
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe: rain hood

24. UNATTACHED, SMALL OUTBUILDINGS
Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed: windows covered with wood inserts; new glass panel door.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.
Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION
Sources of information: field survey

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7TIL9a,9b Date taken: 05/25/87 Photographer: Barry Thorne

29. NAME OF PREPARER: Barry Thorne DATE: 07/16/87

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: $4,456

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: Addition to school also part of this allocation.

INVENTORY OF WPA RESOURCES NOT SUITABLE FOR NATIONAL REGISTER

TILLMAN COUNTY

(Region 7)

	Property Name	Location	Town	Photo Ref.
1.	Laing School	T1N, R18W, SE22	Tipton vic	7TIL10a,b

HISTORIC PRESERVATION SURVEY INVENTORY FORM Figure "D"

1. PROPERTY NAME: Laing School

2. PROPERTY ADDRESS Street Address:
City: Tipton (vic) County: Tillman
State: OK Zip Code: 73570 Region: 7


3. PROPERTY LOCATION Lot: Township: 1N
Block or Section: SE22 Range: 18W

4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:

6. Identification uncertain:

7. Unable to locate:

8. Warrant further study National Register: no



9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:

10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:

11. CONDITION OF RESOURCE Excellent: Good: Fair: Poor: x

12. ORIGINAL SITE Yes: x No: Date moved and from where:

13. ARCHITECT/BUILDER: Year Built: 1939

14. ACCESSIBLE Yes: x No:

15. PRESENT USE
Agriculture: x Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: Religious: Other:

BUILDING CONSTRUCTION DESCRIPTION

16. NUMBER OF STORIES: 1 Full: 1 Partial: Below Ground:

17. FOUNDATION TYPE Stone: Brick: Concrete: x Other:

18. ROOFING MATERIAL Historic: Present: composition
Roof type Hipped: Shed: Flat: x Gabled:
Other: arched

19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present: x
Masonry, bearing: Type Brick: Stone: Type:
Other, describe: poured concrete

20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:

21. DOORS Material and type. Historic: Present:
Style: Wood: Metal: Single: Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURES
Tower: projectir joined: other:
Entries: Pedimente Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe: parapets

24. UNATTACHED, SMALL OUTBUILDINGS
Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed: north wall knocked out for barn usage; several window openings covered with concrete block; all windows and doors missing.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.
Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION
Sources of information: field survey

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7TIL10a,10b Date taken: 05/25/87 Photographer: Barry Thorne

29. NAME OF PREPARER: Barry Thorne DATE: 07/16/87

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: $48,346

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: The allocation also included a garage. The garage could not be located.